

LINDY®

CONNECTION PERFECTION
USB MIDI Interface



www.lindy.com

Quick Installation Guide

1. Connect the cable marked "IN" to the MIDI "OUT" socket of a MIDI Keyboard (or another MIDI device)
2. Connect the cable marked "OUT" to the MIDI "IN" socket of a MIDI Keyboard (or another MIDI device)
3. Plug the USB connector into any available USB socket in your computer, the power LED will light
4. Open your music software and set the MIDI in and MIDI out devices to "USB Audio Device"
5. Your USB MIDI interface is now ready for use
6. It is recommended to always use this interface on the same USB connector in order to avoid multiple driver installations.

LINDY No. 06100

